

	GROUPS A/B/B1/B2/C1/D/M				
	SCRATCH		DENT		REPLACEMENT BREAKING MISSING PART
	LIGHT	SERIOUS	LIGHT	SERIOUS	
BODYWORK					
Front fender	€ 165	€ 275	€ 275	€ 385	€ 660
Rear fender	€ 195	€ 330	€ 330	€ 400	€ 700
Front door	€ 195	€ 330	€ 305	€ 440	€ 990
Rear door	€ 195	€ 330	€ 305	€ 440	€ 990
Sill	€ 110	€ 220	€ 220	€ 385	€ 660
Front hood	€ 165	€ 330	€ 305	€ 440	€ 770
Rear hood or talgate	€ 165	€ 305	€ 305	€ 495	€ 1.200
Roof	€ 275	€ 385	€ 330	€ 550	€ 1.600
Front bumper	€ 200	€ 400	€ 200	€ 385	€ 550
Rear bumper	€ 200	€ 400	€ 200	€ 385	€ 550
Manual external rearview (excluding glass)	€ 45	€ 150	€ 90	€ 165	€ 195
Electric external rearview (excluding glass)	€ 55	€ 110	€ 110	€ 165	€ 220
Car door handle (Lock <u>NOT</u> damaged)	€ 25	€ 50	€ 35	€ 50	€ 500
Plate	€ 50	€ 150	€ 50	€ 150	€ 500
Fuel cap	€ 50	€ 150	€ 50	€ 150	€ 500
Internal rearview mirror	€ 120				
Front bumper moulding	€ 200				
Front/back bumper bracket (moulding position lamp)	€ 20				
Front bumper cover moulding	€ 120				
Front bumper escutcheon	€ 50				
Front and rear cap bumper	€ 50				
Front bumper grid	€ 80				
Front bumper spoiler	€ 120				
Front bumper surround	€ 60				
Front bumper lower corner moulding	€ 80				
Front underbody moulding	€ 120				
Rear bumper lower corner moulding	€ 80				
Rear bumper guard moulding	€ 160				
Rear bumper moulding	€ 200				
Rear underbody moulding	€ 120				
Door moulding	€ 100				
Sill moulding	€ 100				
Front fender moulding	€ 100				
Rear fender moulding	€ 250				
Roof moulding	€ 250				
Lock or Key	€ 280				
Emblem	€ 50				
RIMS AND TYRES					
Alloy rims	€ 85	€ 165	€ 165	€ 165	€ 260
Iron rims	€ 55	€ 110	€ 135	€ 135	€ 135
Hubcap	€ 25	€ 40	€ 40	€ 50	€ 50
Tyre	€ 165				
Kit tyre repair	€ 195				
GLASSES					
Front door glass	€ 165				
Rear door glass	€ 195				
Front and rear door fixed glass	€ 165				
Rear window	€ 420				
Windscreen	€ 475				
Glass ceiling	€ 660				
Rearview mirror glass (interior)	€ 80				
Side turn indicator	€ 30				

Headlamp (NO xenon headlights)	€ 220
Headlamp (xenon headlights / led)	€ 880
Fog lamp	€ 135
Rear light assembly	€ 165
INTERIORS	
Extra wash	€ 70
Veichle sanification	€ 80
Upholstery and interior finishes	€ 220
Hatbox surface	€ 100
High 2isibilità jacket	€ 25
Warning triangle	€ 25
Car documents	€ 200
Smoking ban violation	€ 100